

## A38 Package of work scheme e-bulletin – w/c 18 May 2020

Welcome to this week's traffic management bulletin for the package of work that we're delivering on the A38.

Restrictions in place 24/7 for the duration of the work:

- Narrow lanes in place on the southbound A38 through Barton Turn and the 50mph speed limits are being enforced via speed camera.
- On the local road above the A38 at Barton Turn (B5016/Station Road) 3-way traffic lights in operation to allow us to work on our repairs to the bridge.
- A38 northbound exit slip to Toyota Island (for A50) reduced to single lane 24/7

This coming week will see us work within our existing traffic management on the Barton Turn structure and the A38 northbound exit slip road at Toyota Island. The following week will see us focus on Swinfen roundabout just south of Lichfield.

We're sorry for any disruption that our work may cause you; please plan and allow extra time for your journey. For up to date details of closures on our network please check the <u>Roadworks finder</u>. We also have a twitter feed you can follow <u>here</u> for roadworks notifications. For further information about our work, please contact: <u>info@highwaysengland.co.uk</u>



## Week commencing 18 May 2020 Traffic Management

We issue these bulletins weekly, if you wish to be added to the distribution list please email: <a href="mailto:noreplyA38WMids@highwaysengland.co.uk">noreplyA38WMids@highwaysengland.co.uk</a>

Date	Traffic Management Details	Times	Work activity
Monday 18 May	Southbound Northbound		Working within existing traffic management on Barton Turn Bridge and northbound exit slip to Toyota Island
Tuesday 19 May	Southbound Northbound		Working within existing traffic management on Barton Turn Bridge and northbound exit slip to Toyota Island
Wednesday 20 May	Southbound Northbound		Working within existing traffic management on Barton Turn Bridge and northbound exit slip to Toyota Island
Thursday 21 May	Southbound Northbound		Working within existing traffic management on Barton Turn Bridge and northbound exit slip to Toyota Island
Friday 22 May	Southbound Northbound		Working within existing traffic management on Barton Turn Bridge and northbound exit slip to Toyota Island
Saturday 23 May	Southbound Northbound		Working within existing traffic management on Barton Turn Bridge and northbound exit slip to Toyota Island
Sunday 24 May	Southbound Northbound		Working within existing traffic management on Barton Turn Bridge and northbound exit slip to Toyota Island

## Week commencing 25 May 2020 Traffic Management

We issue these bulletins weekly, if you wish to be added to the distribution list please email: <a href="mailto:noreplyA38WMids@highwaysengland.co.uk">noreplyA38WMids@highwaysengland.co.uk</a>

Date	Traffic Management Details	Times	Work activity
Monday 25 May	Southbound A38 exit slip road for Swinfen roundabout (where A38 meets the A5148) reduced to one lane	8pm – 6am	Renewal of road markings on the roundabout
	Northbound A38 Barton Turn exit and entry slip roads closed	8pm – 6am	Applying the anti-skid surface on the slip roads
	West half of Swinfen roundabout closed – No access from London Road (from Cricket Lane) or the A5148	8pm – 6am	Renewal of road markings on the roundabout
Tuesday 26 May	Southbound A38 exit slip road for Swinfen roundabout (where A38 meets the A5148) reduced to one lane	8pm – 6am	Renewal of road markings on the roundabout
	Northbound West half of Swinfen roundabout closed – No access from London Road (from Cricket Lane) or the A5148	8pm – 6am	Renewal of road markings on the roundabout
Wednesday 27 May	Southbound A38 exit slip road for Swinfen roundabout (where A38 meets the A5148) closed. East half of Swinfen	8pm – 6am	Renewal of road markings on the roundabout
	roundabout closed including the A38 southbound between Swinfen roundabout and Weeford Interchange.	8pm – 6am	Renewal of road markings on the roundabout
	Northbound A38 closed between Weeford Interchange and Swinfen roundabout	8pm – 6am	Renewal of road markings on the roundabout

Thursday 28 May	Southbound A38 exit slip road for Swinfen roundabout (where A38 meets the A5148) closed. East half of Swinfen roundabout closed including	8pm – 6am 8pm – 6am	Renewal of road markings on the roundabout  Renewal of road markings on the roundabout
	the A38 southbound between Swinfen roundabout and Weeford Interchange.		
	Northbound A38 closed between Weeford Interchange and Swinfen roundabout	8pm – 6am	Renewal of road markings on the roundabout
Friday 29 May	Southbound A38 exit slip road for Swinfen roundabout (where A38 meets the A5148) closed.	8pm – 6am	Renewal of road markings on the roundabout
	East half of Swinfen roundabout closed including the A38 southbound between Swinfen roundabout and Weeford Interchange.	8pm – 6am	Renewal of road markings on the roundabout
	Northbound A38 closed between Weeford Interchange and Swinfen roundabout	8pm – 6am	Renewal of road markings on the roundabout
Saturday 30 May	Southbound A38 exit slip road for Swinfen roundabout (where A38 meets the A5148) closed.	8pm – 6am	Renewal of road markings on the roundabout
	East half of Swinfen roundabout closed including the A38 southbound between Swinfen roundabout and Weeford Interchange.	8pm – 6am	Renewal of road markings on the roundabout
	Northbound A38 closed between Weeford Interchange and Swinfen roundabout	8pm – 6am	Renewal of road markings on the roundabout
Sunday 31 May	Southbound Northbound		

**NOTE:** Our planned road work may be subject to change due to weather conditions or unforeseen circumstances. Where possible, we will notify you if there are any changes to the schedule.

Please direct all enquiries to the Highways England Customer Contact Centre on 0300 123 5000, or email <a href="mailto:info@highwaysengland.co.uk">info@highwaysengland.co.uk</a>.