

A38 Package of work scheme

e-bulletin – w/c 1 June 2020

Welcome to this week's traffic management bulletin for the package of work that we're delivering on the A38.

We are always looking for your feedback and have launched a website which allows you to have your say regarding our work and how we are communicating with you. Please follow the link [here](#).

Last week we worked over the bank holiday when traffic counts are lower to help reduce the impact of our work on the travelling public. A photo below shows some of the work we were doing. We will be finishing the markings at Swinfen roundabout this week. We'll be installing temporary barriers on the Toyota Island northbound exit slip road from Wednesday. This will result in the slip being reduced to one lane until we finish rectifying some issues following a landslide in the area.

Restrictions in place 24/7 for the duration of the work:

- Narrow lanes in place on the southbound A38 through Barton Turn and the 50mph speed limits are being enforced via speed camera.
- On the local road above the A38 at Barton Turn (B5016/Station Road) 3-way traffic lights in operation to allow us to work on our repairs to the bridge.

We're sorry for any disruption that our work may cause you; please plan and allow extra time for your journey. For up to date details of closures on our network please check the [Roadworks finder](#). We also have a twitter feed you can follow [here](#) for roadworks notifications. For further information about our work, please contact: info@highwaysengland.co.uk



Week commencing 1 June 2020 Traffic Management

We issue these bulletins weekly, if you wish to be added to the distribution list please email: noreplyA38WMids@highwaysengland.co.uk

Date	Traffic Management Details	Times	Work activity
Monday 1 June	Southbound A38 exit slip road for Swinfen roundabout (where A38 meets the A5148) closed.	8pm – 6am	Renewal of road markings on the roundabout
	East half of Swinfen roundabout closed including the A38 southbound between Swinfen roundabout and Weeford Interchange.	8pm – 6am	Renewal of road markings on the roundabout
	Northbound A38 closed between Weeford Interchange and Swinfen roundabout	8pm – 6am	Renewal of road markings on the roundabout
Tuesday 2 June	Southbound A38 exit slip road for Swinfen roundabout (where A38 meets the A5148) closed.	8pm – 6am	Renewal of road markings on the roundabout
	East half of Swinfen roundabout closed including the A38 southbound between Swinfen roundabout and Weeford Interchange.	8pm – 6am	Renewal of road markings on the roundabout
	Northbound A38 closed between Weeford Interchange and Swinfen roundabout	8pm – 6am	Renewal of road markings on the roundabout
Wednesday 3 June	Southbound A38 exit slip road for Swinfen roundabout (where A38 meets the A5148) closed.	8pm – 6am	Renewal of road markings on the roundabout
	East half of Swinfen roundabout closed including the A38 southbound between Swinfen roundabout and Weeford Interchange.	8pm – 6am	Renewal of road markings on the roundabout
	Northbound A38 closed between Weeford Interchange and Swinfen roundabout	8pm – 6am	Renewal of road markings on the roundabout
	A38 Toyota Island exit slip road closed	8pm – 6am	Removal of Lighting column and associated tasks

Thursday 4 June	Southbound A38 exit slip road for Swinfen roundabout (where A38 meets the A5148) closed. East half of Swinfen roundabout closed including the A38 southbound between Swinfen roundabout and Weeford Interchange.	8pm – 6am	Renewal of road markings on the roundabout
	Northbound A38 closed between Weeford Interchange and Swinfen roundabout	8pm – 6am	Renewal of road markings on the roundabout
	A38 Toyota Island exit slip road closed	8pm – 6am	Installation of traffic management to reduce the slip road to one lane
Friday 5 June	Southbound A38 exit slip road for Swinfen roundabout (where A38 meets the A5148) closed. East half of Swinfen roundabout closed including the A38 southbound between Swinfen roundabout and Weeford Interchange.	8pm – 6am	Renewal of road markings on the roundabout
	Northbound A38 closed between Weeford Interchange and Swinfen roundabout	8pm – 6am	Renewal of road markings on the roundabout
	A38 Toyota Island exit slip reduced to one lane	24 hours	Ground work to rectify landslide
Saturday 6 June	Southbound A38 exit slip road for Swinfen roundabout (where A38 meets the A5148) closed. East half of Swinfen roundabout closed including the A38 southbound between Swinfen roundabout and Weeford Interchange.	8pm – 6am	Renewal of road markings on the roundabout
	Northbound A38 closed between Weeford Interchange and Swinfen roundabout	8pm – 6am	Renewal of road markings on the roundabout
	A38 Toyota Island exit slip reduced to one lane	24 hours	Ground work to rectify landslide
Sunday 7 June	Southbound Northbound A38 Toyota Island exit slip reduced to one lane	24 hours	Ground work to rectify landslide

Week commencing 8 June 2020 Traffic Management

We issue these bulletins weekly, if you wish to be added to the distribution list please email: noreplyA38WMids@highwaysengland.co.uk

Date	Traffic Management Details	Times	Work activity
Monday 8 June	Southbound Northbound A38 Toyota Island exit slip reduced to one lane	24 hours	Ground work to rectify landslide
Tuesday 9 June	Southbound Northbound A38 closed between Branston junction and Claymills junction A38 Toyota Island exit slip reduced to one lane	8pm – 6am 24 hours	Drainage repairs and upgrades Ground work to rectify landslide
Wednesday 10 June	Southbound Northbound A38 closed between Branston junction and Claymills junction A38 Toyota Island exit slip reduced to one lane	8pm – 6am 24 hours	Drainage repairs and upgrades Ground work to rectify landslide
Thursday 11 June	Southbound Northbound A38 closed between Branston junction and Claymills junction A38 Toyota Island exit slip reduced to one lane	8pm – 6am 24 hours	Drainage repairs and upgrades Ground work to rectify landslide
Friday 12 June	Southbound Northbound A38 closed between Branston junction and Claymills junction A38 Toyota Island exit slip reduced to one lane	8pm – 6am 24 hours	Drainage repairs and upgrades Ground work to rectify landslide
Saturday 13 June	Southbound Northbound A38 Toyota Island exit slip reduced to one lane	24 hours	Ground work to rectify landslide
Sunday 14 June	Southbound Northbound A38 Toyota Island exit slip reduced to one lane	24 hours	Ground work to rectify landslide

NOTE: Our planned road work may be subject to change due to weather conditions or unforeseen circumstances. Where possible, we will notify you if there are any changes to the schedule.

Please direct all enquiries to the Highways England Customer Contact Centre on 0300 123 5000, or email info@highwaysengland.co.uk.